

## **INSPECTION HISTORY**

## ROF2017-00909, Roof, TEAR OFF EXISTING TILE AND INSTALL NEW UNDERLAYMENT AND TILE

INSPECTION TYPE 501 Roof Dry In	<b>REQUESTED DATE</b> 04/27/2017	<b>SCHEDULED DATE</b> 04/28/2017	<b>INSPECTED DATE</b> 04/28/2017	<b>STATUS</b> Fail	comments need to seal under leading edge of dryin where not on selvedge . horizonal and vertical laps , marked examples check all	INSPECTOR NAME/PHONE Morgan L Highfill / 239-849-3389
501 Roof Dry In	04/28/2017	05/01/2017	05/01/2017	Already Done	[2397341674]	Morgan L Highfill / 239-849-3389
502 Roof In Process	05/16/2017	05/17/2017	05/17/2017	Already Done		Morgan L Highfill / 239-849-3389
503 Final Roof	05/25/2017	05/26/2017	05/26/2017	Already Done	[2397341674]	Dempsey H Vick / 239-850-2731

Page 1 of 1 flnspHistory.rpt