

INSPECTION HISTORY

ROF2017-00924, Roof, TEAR OFF EXISTING TILE ROOF AND INSTALL NEW UNDERLAYMENT AND TILE

INSPECTION TYPE	REQUESTED DATE	SCHEDULED DATE	INSPECTED DATE	STATUS	COMMENTS	INSPECTOR NAME/PHONE
501 Roof Dry In	09/25/2017	09/26/2017	09/26/2017	Fail	Valley apex in JCT with hip and ridge attachments restricting water flow.	Dempsey H Vick / 239-850-2731
501 Roof Dry In	10/23/2017	10/24/2017	10/24/2017	Already Done	[2398989740] Ck bottom of valley over front entry way for water run off at 503.	Dempsey H Vick / 239-850-2731
502 Roof In Process	10/27/2017	10/30/2017	10/30/2017	Already Done	[2398989740]	Dempsey H Vick / 239-850-2731
503 Final Roof	12/07/2017	12/08/2017	12/07/2017	Cancel	[2398989740]	/
503 Final Roof	12/07/2017	12/08/2017	12/07/2017	Cancel	[2398989740]	/
503 Final Roof	12/07/2017	12/08/2017	12/07/2017	Cancel	[2398989740]	/
503 Final Roof	12/07/2017	12/08/2017	12/07/2017	Cancel	[2398989740]	/
503 Final Roof	01/19/2018	01/22/2018	01/25/2018	Fail	[2398989740] Top of flashing not water tight,)right side of entry way at 8569). Down spout running water through tile on to tile underlayment,(right side of entry way at 8569).	Dempsey H Vick / 239-850-2731
503 Final Roof	02/02/2018	02/05/2018	02/05/2018	Already Done	[2398989740]	Dempsey H Vick / 239-850-2731